


# CRESCENT HOUSE



- 1 bush-hammered, in situ concrete bands
- 2 hardwood timber window frames
- 3 pivoting centrally hung casements
- 4 aluminium opening lights
- 5 georgian wired glass
- 6 white infill panels (spandrel panels)
- 7 stepped profile of the building along the curve of the road
- 8 mosaic tiles on exposed floor slab edges
- 9 rendered concrete cross walls, painted rust-red
- 10 built in timber 'floating' shelves




Deterioration of the hardwood frame/cill on the west façade where the glass pane has become exposed to the elements. Evidence of mould growth.



Deterioration of the softwood frame/cill on the kitchen window facing the internal lightwells.




Deterioration of the hardwood frame/vv on the west façade (oriel window).




Paintwork deteriorating on timber frame and the spandrel panel. Evidence of mould growth.

## NOW



- Key**
- Heat loss through single glazing
  - ⋯→ Heat loss through external walls & thermal bridges (incl. window frame)
  - ~> Uncontrolled incoming air (draughts)
  - > Excess solar gains (summer)
  - Noise pollution
  - Air pollution
  - Mould growth
  - Condensation build-up

## CHALLENGES



## PROPOSAL




# CRESCENT HOUSE PILOT PROJECT

## TESTING OF EXISTING BUILDING FABRIC

A suite of tests has been carried out by the BRE to provide indicative performance characteristics of the existing window systems. These tests provide baseline data. The tests will be re-run following refurbishment & installation of vacuum glazing in the windows, and the improved performance compared against the baseline data.

### AIRTIGHTNESS TESTING

The airtightness of the external façades was tested using a blower door to pressurise the apartment, and smoke pens to show air leakage paths. This showed significant air leakage paths around window frames. The test will be re-run following refurbishment of the window frames & installation of the vacuum glazing to measure the reduction of air leakage.




Above: air leakage paths through/around the window frames demonstrated using a smoke pen




Above: blower door test equipment mounted in the front door

### ACOUSTIC TESTING

The amount of noise admitted through the façade on Goswell Road was tested using sound meters/microphones measuring the noise externally & internally for a period of seven days. This showed that the existing windows have poor acoustic performance, which is likely to be made worse by the significant air leakage paths. The test will be re-run following refurbishment of the window frames & installation of the vacuum glazing to measure the reduction in noise transmission.




Above: microphone measuring external noise levels



Above: microphone/sound meter measuring internal noise levels

### THERMAL TESTING

An infrared camera was used to carry out a thermographic survey and determine where conductive heat loss, structural defects, air leakage and thermal bridging within the building fabric occur. This showed localised heat loss around door penetrations, pipe work and window frames, as well as in the kitchen & oriel window roofs and the bookshelf on the external façade. The test will be re-run following refurbishment of the window frames & installation of the vacuum glazing and insulation to the main concrete vaulted roofs, first floor concrete soffit & bookshelf, to determine the reduction in heat loss.



Above: infrared photographs showing key heat loss junctions around the flat. A darker colour indicates higher levels of heat loss, which may lead to condensation and mould developing in that area.



## AIR LEAKAGE

## NOISE

## THERMAL




# GENERAL PROCESS




- ①
- Install scaffold
  - Temporarily remove existing glass to template for new vacuum glazing
  - Measure glass and place order
  - Establish extent of repair needed for the frames and estimate programme for the repair works
  - Put existing glass back in

## MEASURE



- ②
- Strip decorations on existing frames, remove the existing glass and opening casements, and repair damaged frames to coincide for them to finish at the time of the glass delivery
  - Replace any damaged sections of frame that cannot be repaired
  - Insert new perimeter seals into opening lights
  - Redecorate frames

## REPAIR



- ③
- Install new vacuum glass and beads
  - Make good decorations to surrounding areas

## NEW GLASS